

## **Maintenance and treatment of black spots on pre-weathered wood**

Black spots are caused by moisture in the wood. The pre-weathering process involves a bleaching agent that attracts moisture, which in turn can make thermally modified wood more susceptible to mould. This makes it very important to ensure good ventilation at all times.

Mould is a natural phenomenon that affects the appearance of wood, but not its durability. The black spots should disappear in time. If you prefer not to wait, you can easily treat it with the same bleaching agent that is used in the pre-weathering process.

### **Instructions**

1. This product may cause irritation in contact with skin or eyes. Therefore, gloves and eye protection are recommended.
2. Apply product to cladding with a large brush and allow to dry.

*Note: product should only be used at an ambient temperature of > 15°C.*

After treatment, your cladding should look as good as new.

If you want to use the bleaching agent on your wood, please let us know and we will send it to you.